

# ADA SURVEY RESULTS

## Survey Results - by Building / Element

### City of Beauty ADA Survey

#### Test Building

345 Main St. Anytown, CA

Date: 8/25/2005

Page: 1

LOCATION	RECOMMENDATION	COMMENTS	TYPE CODE	PRI	QTY	UNITS	BUDGET
----------	----------------	----------	-----------	-----	-----	-------	--------

#### Accessible Parking

<b>Barrier</b>   100	<p>The parking area lacks the required quantity of standard accessible stalls or van-accessible stalls, or existing accessible stalls are non-compliant. [NEW ADAAG: Allows 11'-0" wide van stalls plus 5'-0" wide access aisle, or 8'-0" wide van stall plus 8'-0" wide access aisle. Angled van stalls require access aisles located on passenger side of the space.]</p>	<p><b>ADAAG Citation</b>   ADAAG 4.6.1, 4.6.4, 4.1.2 (5)(b)</p> <p><b>New ADAAG</b>   502.2; 502.3.4</p>
----------------------	---	--

<b>MAIN PARKING LOT</b>	<p>Restripe existing area with 3 new accessible stalls and 1 new van-accessible stalls. Add 2 signs displaying the International Symbol of Accessibility.</p>	<p>Budget cost includes striping and signage. ADAAG Requirements: Accessible stall quantity required: (1 to 25)= 1, (26 to 50)= 2, (51 to 75)= 3, (76 to 100)= 4, (101 to 150)= 5, (151 to 200)= 6, (201 to 300)= 7, (301 to 400)= 8, (401 to 500)= 9, (501 and 1000)= 2% of total, (1001 and over)= 20 plus 1 for each 100 over 1000. Note that 1 access aisle may be shared between 2 stalls. In addition, 1 van-accessible stall is required for every 8 required standard accessible stalls, with minimum of 1. Stall size requirements: standard stall = 8'-0" wide with 5'-0" aisle; van stall = 8'-0" wide with 8'-0" aisle.</p>	<p>P 1 1 0.5 DAY</p>	<p>\$980.00</p>
-------------------------	---	---	----------------------	-----------------

#### Doors

<b>Barrier</b>   201	<p>The door lacks the required maneuvering space, or the maneuvering space is not level.</p>	<p><b>ADAAG Citation</b>   ADAAG 4.13.6 (Fig.25)</p> <p><b>New ADAAG</b>  </p>		
<b>MEETING ROOM</b>	<p>Relocate the door/frame to provide door maneuvering space.</p>	<p>Assure door maneuvering spaces (min. 18" at the pull-side and min. 12" at the push-side); Provide clear floor space (min. 60" perpendicular to door for front/pull-side approach and 48" perpendicular to door for front or side/push-side approach (latch and closer) or 42" perpendicular to door for a front or side/ push-side approach (without latch and closer).</p>	<p>P 1 2 1 EA</p>	<p>\$1,410.00</p>