



Upper Left: Women's Public Restroom Entry area. The telephone (located in the alcove) lacks maneuvering space. The signage (at Women's Public and Men's Public Restrooms) is mounted higher than 60" (measured at centerline of sign).

Upper Right: Men's Public Restroom. The security panel (at the Baby Changing area) encroaches on door maneuvering space (required depth) at entry door. The top of security panel is too high to be accessible (measured at 39" AFF).

Lower Left: Men's Public Restroom. The bottom edge of the mirror is mounted higher than 40" maximum. The sink lacks pipe wrapping (Typical).

SAMPLE BUILDING - Any City, State